

Work Order ID 102631

Tuesday, June 04, 2013 1:36:44 PM

102631

Page 1

Item ID: D3536-13

Accept

N9000040100

Setup Start

NS1

Revision ID:

Item Name: Gasket

Stop

NS2

Start Date: 6/4/2013 Start Qty: 1.00

1

Cust Item ID:

Required Date: 6/5/2013 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111550

Approvals: Process Plan: *MF*Date: *13-6-04*

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3536

Rev A

100

0.00

100

QC

Memo

0.00

Quality Control

INSPECT RA 111550 D3536-13 X 1 B#95875

PART IS GOOD

RETURN TO STOCK UNDER NEW BATCH NUMBER

110

Identify as per dwg & Stock Location: *FP-601* 0.00***110***

Packaging

Memo

0.00

Packaging

120

QC21- Final Inspection - Work Order Release 0.00

120

QC

Memo

0.00

Quality Control

*X1 d M13/06/07**ML5 13-06-07**ML5 13-06-07*

Picklist Print

Tuesday, June 04, 2013 1:36:43 PM

Page 1

Work Order ID: 102631

Parent Item: D3536-13

Parent Item Name: Gasket

Start Date: 6/4/2013

Required Date: 6/5/2013

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A New Issue 07-02-14 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3536-13 Gasket		Manufactured	No				Each	9.0000		1			

Location

Loc Qty

Loc Code

FG

6

81344

2

89686

4

FP001

3

95875

3

1 x 95875
MF
1364

RA111550

Received @ Dart May 31st, 2013
Inspected @ Dart June 4th, 2013

CUSTOMER: MIRABEL HELI SUPPORT
CUSTOMER CONTACT: CATHERINE MCLOED
SHIPPED FROM: MIRABEL PQ, CANADA

Instructions for RA 111550 D3535-13 B95958

- Return to stock no defects found
- Return to stock under new Batch #

Instructions for RA 111550 D3536-13 B95875

- Return to stock no defects found
- Return to stock under new Batch #

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = x1 D3535-13 B95958
x1 D3536-13 B95875

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**